



## Errata

# NFPA 101<sup>®</sup>

## *Life Safety Code*<sup>®</sup>

### 2018 Edition

**Reference:** A.8.3.3.2.2

**Errata No:** 101-18-3

The Technical Committee on Fire Protection Features and the Correlating Committee on Safety to Life notes the following error in the 2018 edition of NFPA 101<sup>®</sup>, *Life Safety Code*<sup>®</sup>.

1. Delete the second A.8.3.3.2.2, which was inadvertently added to the document, as follows:

*N A.8.3.3.2.2* Longer ratings might be required where opening protectives are provided for property protection as well as life safety. NFPA 80 should be consulted for standard practice in the selection and installation of fire door assemblies and fire window assemblies.

A vision panel in a fire door is not a fire window, and, thus, it is not the intent of the “NP” notations in the “Fire Window Assemblies” column of Table 8.3.3.2.2 to prohibit vision panels in fire doors.

~~A A.8.3.3.2.2~~ Longer ratings might be required where opening protectives are provided for property protection as well as life safety. NFPA 80 should be consulted for standard practice in the selection and installation of fire door assemblies and fire window assemblies.

~~A vision panel in a fire door is not a fire window, and, thus, it is not the intent of the “NP” notations in the “Fire Window Assemblies” column of Table 8.3.5.2 to prohibit vision panels in fire doors.~~

Issue Date: November 18, 2019

(Note: Electronic products and pamphlet reprints may have this errata incorporated. For current information about the NFPA Codes and Standards, including this errata, please see [www.nfpa.org/docinfo](http://www.nfpa.org/docinfo))

Copyright © 2019 All Rights Reserved  
NATIONAL FIRE PROTECTION ASSOCIATION